








| | | | |
|---------------------|--------|----------------------|-------------------|
| Organisation | ACME | <h1>Red Tag Log</h1> | Created by |
| Area | Cell 1 | | C Brown |
| Page Number. | 1 | | |

| Tag Number | Location | Date Raised & Initials | Abnormal Conditions | Countermeasure | Person Responsible | Target Completion Date | Status |
|------------|------------------------|------------------------|---------------------------|--------------------------|--------------------|------------------------|---|
| 001 | Storage rack top shelf | 30/09/2006 CB | Label out of date | Re-label to new standard | Team member | Week 7 |  |
| 002 | Ceiling | 30/09/2006 CB | Light bulb not working | Replace bulb | Electrician | Week 6 |  |
| 003 | Machine 20 | 30/09/2006 CB | Oil leak on rear pump | Fix source of leak | Maintenance | Week 8 |  |
| 004 | Computer | 30/09/2006 CB | Duplicate files on system | Archive duplicates | Team member | Week 6 |  |
| | | | | | | |  |
| | | | | | | |  |
| | | | | | | |  |

 Responsibility allocated
  Countermeasure underway
  Countermeasure completed
  Countermeasure checked and ok